MAHARASHTRA JEEVAN PRADHIKARAN

4th Floot, Express Towars, Nariman Point, Mumbai - 400 021 (India)



Phone : 202 8249 302 5354 283 5247 Fax : 202 9348 STD : 022 Gram : PANIMANDAL, Mumbal.

TECHNICAL CIRCULAR NO. - 3 /

Date: 22.10.1999

No.MS/TS-II/Circular/ 3/74

On C.I. and D.I. Pipelines, C.I. specials as well as M.S. Specials and fittings are being used with lead joints; due to non availability of C.I. and D.I. specials and fittings with rubber joints.

This is most undesirable since pig lead joints are troublesome. There is also a possibility of increase in the Lead content in drinking water, which is hazardous to health.

Now Mechanical Joints and fittings are available on R.C. made by M.I.P. Therefore, suless the specific site conditions require lead joints, all jointing / repairs can be carried out by using Mechanical Joints and Fittings with rubber joints, where indispensable.

All field officers should note this and act accordingly.

D.A.: Nil.

(R.M. Sagano) Member Secretary (Tech.)

C.C.

Officer On Special Duty and Chief Engineer, M.J.P., Navi Mumbai.
All Chief Engineers.

All Superintending Engineers.
All Executive Engineers.

M. J. C.